

Address: NO. 8, LANE 29, WENMING RD., LESHAN VILLAGE, GUISHAN SHIANG, TAOYUAN COUNTY, 333, TAIWAN, R.O.C.

TEL: 886-3-328-0026 ext 291、298

FAX: 886-3-327-6176

TESTING REPORT

Company: GEOVISION INC.

Address: 9F., No.246, Sec.1, Neihu Rd., Neihu District, Taipei 114,

Taiwan R.O.C.

For Office Use

Application No.:07-01-QAC-078

Reviewed by:

Receive Date: 29th Jan., 2007

Date Issued: 02nd Feb., 2007 Notes:

Total Pages: 3 This Page: 1

1. This report is based on single evaluation of the sample mentioned in testing results. It doesn't imply an assessment of the whole production.

2.The content of this report is for references, but not for advertising publicity or other commercial purpose

3. The testing report shall not be reproduced except in full, without the written approval of ETC.



Electronics Testing Center,

oping

Manager Lab. Leader

Testing Item & Experimental:

| Analytical Substance | Equipments | |
|----------------------|---|--|
| Elements Analysis | X-Ray Fluorescence Spectrometer (SEKIO 1000A) (SPECTRO XEPOS) | |

Result:

Address: NO. 8, LANE 29, WENMING RD., LESHAN VILLAGE, GUISHAN SHIANG, TAOYUAN COUNTY, 333, TAIWAN, R.O.C.

TEL: 886-3-328-0026 ext 291、298

FAX: 886-3-327-6176

TESTING REPORT

Company: GEOVISION INC.

Address: 9F., No.246, Sec.1, Neihu Rd., Neihu District, Taipei 114,

Taiwan R.O.C.

For Office Use

Application No.:07-01-QAC-078

Reviewed by:

Receive Date: 29th Jan., 2007 Date Issued: 02nd Feb., 2007

Notes:

Total Pages: 3 This Page: 2

1. This report is based on single evaluation of the sample mentioned in testing results. It doesn't imply an assessment of the whole production.

2. The content of this report is for references, but not for advertising publicity or other commercial purpose

3. The testing report shall not be reproduced except in full, without the written approval of ETC.

Sample Description: GV-DVR System H series **Style/Item No.**: GV2016H,GV2008H,GV1480H,GV1240H,GV1120H

| Elements | Testing Result | | | I lmit |
|----------|----------------|------|------|--------|
| | NO.1 | NO.2 | NO.3 | Unit |
| Cd | 1.5 | 0.0 | 0.0 | ppm |
| Pb | 35.9 | 0.2 | 0.0 | ppm |
| Hg | 0.0 | 0.4 | 0.1 | ppm |
| Br | 340.9 | 0.6 | 3.5 | ppm |
| Cr | 12.8 | 0.0 | 0.0 | ppm |

Sample Description: GV-DVR System H series **Style/Item No.**: GV2016H,GV2008H,GV1480H,GV1240H,GV1120H

| Elements | | Testing Result | Unit |
|----------|------|----------------|------|
| | NO.4 | | |
| Cd | 0.0 | | ppm |
| Pb | 0.0 | | ppm |
| Hg | 0.0 | | ppm |
| Br | 3.3 | | ppm |
| Cr | 0.0 | | ppm |



Address: NO. 8, LANE 29, WENMING RD., LESHAN VILLAGE, GUISHAN SHIANG, TAOYUAN COUNTY, 333, TAIWAN, R.O.C.

TEL: 886-3-328-0026 ext 291, 298

FAX: 886-3-327-6176

TESTING REPORT

Company: GEOVISION INC.

Receive Date: 29th Jan., 2007

Address: 9F., No.246, Sec.1, Neihu Rd., Neihu District, Taipei 114,

Taiwan R.O.C.

For Office Use

Application No.:07-01-QAC-078

Reviewed by:

Total Pages: 3 This Page: 3

Date Issued: 02nd Feb., 2007 Notes:

1. This report is based on single evaluation of the sample mentioned in testing results. It doesn't imply an assessment of the whole production.

2. The content of this report is for references, but not for advertising publicity or other commercial purpose

3. The testing report shall not be reproduced except in full, without the written approval of ETC.



