

Reliability Laboratory

TEST REPORT

Report No.: HC10170/2013 Page: 1 of 5 February 7, 2013 Date:

GEOVISION INC. 9F, NO. 246, SEC. 1, NEIHU RD., NEIHU DISTRICT, TAIPEI CITY, TAIWAN, R.O.C.

The following merchandise was submitted and identified by the vendor as: Product Description: Megapixel H. 264 WDR Arctic Box IP Camera GV-BX1500-E/ No.1 Style/ Item No.: Manufacturer/Vendor: Geovision Inc. Country of Origin: Taiwan Quantity: Total 1 piece Jan. 30, 2013 **Testing Period**: (Client's declaration) The GV-BX2400-E, GV-BX3400-E, GV-BX5300-E, Note: GV-LPR CAM 10A and GV-Hybrid LPR Camera 10R used the identical enclosure.

We have tested the submitted sample(s) as requested and the following results were obtained: Test Required: (According to client's test specification, please see following sheets in detail.)

1. Impact Test

Test Results: -PLEASE SEE ATTACHED SHEETS-

Signed for and on behalf of SGS TAIWAN Ltd.

Winson Tseng Asst. Manager

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com/terms and conditions.htm</u> and, for electronic format documents, subject to Terms and Conditions of Electronic Documents at <u>www.sqs.com/terms -edocument.htm</u>. Attention of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the client or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

No.31, No.33, No.35, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五權路 31 號, 33 號, 35 號 SGS Taiwan Ltd. 台灣檢驗科技股份有限公司

No.134, Wu Kung Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五工路 134 號 t (886-2) 2299-3279 f (886-2) 2299-9558 www.tw.sas.com

Member of SGS Group



Reliability Laboratory

TEST REPORT

Report No.:	HC10170/2013		
Page:	2	of	5

Name	Brand	Model	Serial No.
Impact Tester	CHUN YEN	-	
Lab Environmental Cond	itions:		
Ambient temperature:	<u>(25 ± 3) °C</u>		
Ambient humidity:	<u>(55 ± 20) % RH</u>		
Test Method/ Specification	on:		
Test method:	Reference to IEC 62262 Edition 1.	0: 2001IK10	
Sample condition:	Non-Operating		
Sample condition: Impact energy:	<u>Non-Operating</u> 20 Joule		
Impact energy:	20 Joule		
Impact energy: Mass:	<u>20 Joule</u> <u>5 kg</u>	<u>2 ~ 6)</u>	
Impact energy: Mass: Impact height:	<u>20 Joule</u> <u>5 kg</u> <u>40 cm</u>	<u>2 ~ 6)</u>	

• Examine the appearance of specimen(s) by visual check after this test.

t (886-2) 2299-3279

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對潮試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com/terms and conditions.htm</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/terms - edocument.htm</u>. Attention of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document document approval of the Company. Any unauthorized alteration, forgery or falsification of the client of the law.

No.31, No.35, No.35, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五摧路 31 號, 33 號, 35 號 No.134, Wu Kung Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五工路 134 號

SGS Taiwan Ltd. 台灣檢驗科技股份有限公司_

f (886-2) 2299-9558



TEST REPORT

Report No.:	HC10170/2013		
Page:	3	of	5

Reliability Laboratory

Specimen:

Style/ Item No.: Quantity: GV-BX1500-E/ No.1 Total 1 piece

Test Result:

	Check Item	Appearance check	
Style/ Item No.		(visual check)	
GV-BX1500-E/ No.1 Posi	Position 1	The specimen was deformed after this test. (see photo 9)	
	Position 2	No visible damage	
	Position 3	No visible damage	
	Position 4	No visible damage	
	Position 5	The specimen was deformed after this test. (see photo 10)	

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對潮試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com/terms and conditions.htm</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/terms - edocument.htm</u>. Attention of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document document approval of the Company. Any unauthorized alteration, forgery or falsification of the client of the law.

No.31, No.33, No.35, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五權路 31 號, 33 號, 35 號 No.134, Wu Kung Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五工路 134 號

SGS Taiwan Ltd. 台灣檢驗科技股份有限公司_

f (886-2) 2299-9558

t (886-2) 2299-3279


www.tw.sgs.com Member of SGS Group



TEST REPORT

Report No.:	HC10170/2013		
Page:	4	of	5

Test Photos:



Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,可時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com/terms and conditions.htm</u> and, for electronic format document is, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/terms - edocument.htm</u>. Attention of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

No.31, No.35, No.35, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五摧路 31 號, 33 號, 35 號 No.134, Wu Kung Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五工路 134 號

SGS Taiwan Ltd. 台灣檢驗科技股份有限公司_

t (886-2) 2299-3279 f (886-2) 2299-9558


www.tw.sgs.com Member of SGS Group



TEST REPORT

Report No.:	HC10170/2013		
Page:	5	of	5

Test Photos--Continued:



— — The End of Test Report — –

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對潮試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>www.sqs.com/terms and conditions.htm</u> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <u>www.sqs.com/terms - edocument.htm</u>. Attention of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document document approval of the Company. Any unauthorized alteration, forgery or falsification of the client of the law.

No.31, No.33, No.35, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五權路 31 號, 33 號, 35 號 No.134, Wu Kung Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五工路 134 號

SGS Taiwan Ltd. 台灣檢驗科技股份有限公司_

t (886-2) 2299-3279 f (886-2) 2299-9558

www.tw.sgs.com Member of SGS Group